



BLISS BOLT REPLACEMENT

Jacobs is pleased to announce a new bolt replacement that will increase the mounting strength of the drive and stiffener ring on the Bliss pellet mills.

- Pictures above show that with the minimal engagement of the standard length bolts the threads can be fatigued and fail, causing die failure.
- OEM thread engagement is 5/8" ; we are increasing engagement to 1 1/8"
- Longer bolts in this size are custom, so Jacobs has decided to stock these in sets for our customers.
- New bolts should be used after two die changes.
- Part Number 145252 BLISS S-RING BOLT SET 16-8 [Includes 16 Drive Bolts, 8 Longer Stiffener Bolts and 24 Washers]
 - 10% off With die purchase
- Jacobs also supplies stiffner rings with 16 bolt holes Part#141131P , Bolt Set #145253

For more information or to purchase bolts, please call 800-831-2005 or email Jacobs@JacobsCorp.com